

Official Laboratory Report

Report To: JEFF MYERS  
SAME  
MI

**Sample ID: LI59067**  
Work Order: 90804404\_08

System Name/Owner:	WEST MIDLAND FAMILY CENTER	WSSN/Pool ID:	20021-56
Collection Address:	4011 W ISABELLA RD,SHEPHERD	Source:	TYPE II
Collected By:	JEFF MYERS	Site Code:	
Township/Well#/Section:	GREENDALE/#5/15	Collector:	Other
County:	Midland	Date Collected:	08/26/2019 08:25
Sample Point:	RAW	Date Received:	08/26/2019 11:09
Water System:	Untreated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Arsenic	0.009	mg/L	0.002	08/27/2019	0.010	EPA 200.8	7440-38-2

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Midland County Health Dept.  
220 West Ellsworth  
Midland, MI 48640-5194  
989 832-6679**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane