

**MICHIGAN DEPARTMENT OF ENVIRONMENTAL QUALITY  
DRINKING WATER LABORATORY**

USEPA Region V Drinking Water Cert. No. MI00003  
P.O. Box 30270  
Lansing, MI 48909  
TEL: (517) 335-8184  
FAX: (517) 335-8562



**Sample Number  
LI31269**

Official Laboratory Report

Report To: JEFF MYERS  
4011 W ISABELLA RD  
SHEPHERD MI 48883

System Name/Owner:	WEST MIDLAND FAMILY CENTER	WSSN/Pool ID:	2002156
Collection Address:	4011 W ISABELLA RD,SHEPHERD	Source:	TYPE II
Collected By:	JEFF MYERS	Site Code:	
Township/Well#/Section:	GREENDALE/5/15	Collector:	Other
County:	Midland	Date Collected:	04/01/2019 09:32
Sample Point:	RAW R	Date Received:	04/01/2019 12:47
Water System:	Untreated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION			REGULATORY INFORMATION			
Analyte Name	Result (mg/L)	Date Tested	RL (mg/L)	MCL/AL (mg/L)	Method	CAS #
Arsenic	0.020	04/03/2019	0.002	0.010	EPA 200.8	7440-38-2

The analyses performed by the MDEQ Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below:**

**Midland County Health Dept.  
220 West Ellsworth  
Midland, MI 48640-5194  
989 832-6679**

CAS# : Chemical Abstract Service Registry Number  
MCL : Maximum Contaminant Level  
AL : Action Level  
RL : Reporting Limit

mg/L : milligrams / Liter (ppm)  
ppm : parts per million  
MPN : Most Probable Number  
CFU : Colony Forming Unit

Laboratory Contact: Scott Hayward

**MICHIGAN DEPARTMENT OF ENVIRONMENTAL QUALITY  
DRINKING WATER LABORATORY**

USEPA Region V Drinking Water Cert. No. MI00003  
P.O. Box 30270  
Lansing, MI 48909  
TEL: (517) 335-8184  
FAX: (517) 335-8562



**Sample Number  
LI31270**

Official Laboratory Report

Report To: JEFF MYERS  
4011 W ISABELLA RD  
SHEPHERD MI 48883

System Name/Owner:	WEST MIDLAND FAMILY CENTER	WSSN/Pool ID:	2002156
Collection Address:	4011 W ISABELLA RD,SHEPHERD	Source:	TYPE II
Collected By:	JEFF MYERS	Site Code:	
Township/Well#/Section:	GREENDALE/5/15	Collector:	Other
County:	Midland	Date Collected:	04/01/2019 10:35
Sample Point:	KITCHEN SINK	Date Received:	04/01/2019 12:47
Water System:	Untreated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION			REGULATORY INFORMATION			
Analyte Name	Result (mg/L)	Date Tested	RL (mg/L)	MCL/AL (mg/L)	Method	CAS #
Arsenic	0.010	04/03/2019	0.002	0.010	EPA 200.8	7440-38-2

The analyses performed by the MDEQ Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below:**

**Midland County Health Dept.  
220 West Ellsworth  
Midland, MI 48640-5194  
989 832-6679**

CAS# : Chemical Abstract Service Registry Number  
MCL : Maximum Contaminant Level  
AL : Action Level  
RL : Reporting Limit

mg/L : milligrams / Liter (ppm)  
ppm : parts per million  
MPN : Most Probable Number  
CFU : Colony Forming Unit

Laboratory Contact: Scott Hayward