

MICHIGAN DEPARTMENT OF ENVIRONMENTAL QUALITY
 DRINKING WATER LABORATORY

USEPA Region V Drinking Water Cert. No. MI00003
 P.O. Box 30270
 Lansing, MI 48909
 TEL: (517) 335-8184
 FAX: (517) 335-8562

Sample Number
 LH70310

Official Laboratory Report

Report To: JEFF MYERS
 4011 W ISABELLA RD
 SHEPHERD MI 48883

System Name/Owner:	WEST MIDLAND FAMILY CENTER	WSSN/Pool ID:	2002156
Collection Address:	4011 W ISABELLA RD, SHEPHERD	Source:	TYPE II
Collected By:	JEFF MYERS	Site Code:	
Township/Well#/Section:	GREENDALE/5/15	Collector:	Public Water Supply Operator
County:	Midland	Date Collected:	03/13/2018 10:40
Sample Point:	RAW	Date Received:	03/13/2018 12:51
Water System:	Untreated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION			REGULATORY INFORMATION			
Analyte Name	Result (mg/L)	Date Tested	RL (mg/L)	MCL/AL (mg/L)	Method	CAS #
Arsenic	0.011	03/14/2018	0.002	0.010	EPA 200.8	7440-38-2

These analyses performed by the MDEQ Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below:

Midland County Health Dept.
 220 West Ellsworth
 Midland, MI 48640-5194
 989 832-6679

CAS# : Chemical Abstract Service Registry Number	mg/L : milligrams / Liter (ppm)	Laboratory Contact: Scott Hayward
MCL : Maximum Contaminant Level	ppm : parts per million	
AL : Action Level	MPN : Most Probable Number	
RL : Reporting Limit	CFU : Colony Forming Unit	