

Official Laboratory Report

Report To: BEN LARSON  
4011 W ISABELLA  
SHEPHERD MI 48883

Sample ID: LJ09521  
Work Order: 00603291\_01

System Name/Owner:	WEST MIDLAND FAMILY CENTER	WSSN/Pool ID:	2002156
Collection Address:	4011 W ISABELLA, SHEPHERD	Source:	TYPE II
Collected By:	BEN LARSON	Site Code:	
Township/Well#/Section:	GREENDALE/5/15	Collector:	Other
County:	Midland	Date Collected:	06/24/2020 08:15
Sample Point:	119A	Date Received:	06/24/2020 12:57
Water System:	Untreated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	0.10	mg/L	0.05	06/25/2020	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	06/25/2020	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

Midland County Health Dept.  
220 West Ellsworth  
Midland, MI 48640-5194  
989 832-6679

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

Report To: BEN LARSON  
4011 W ISABELLA  
SHEPHERD MI 48883

Sample ID: LJ09522  
Work Order: 00603291\_02

System Name/Owner:	WEST MIDLAND FAMILY CENTER	WSSN/Pool ID:	2002156
Collection Address:	4011 W ISABELLA, SHEPHERD	Source:	TYPE II
Collected By:	BEN LARSON	Site Code:	
Township/Well#/Section:	GREENDALE/5/15	Collector:	Other
County:	Midland	Date Collected:	06/24/2020 08:15
Sample Point:	106A NEW GYM	Date Received:	06/24/2020 12:57
Water System:	Untreated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	0.05	mg/L	0.05	06/25/2020	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	06/25/2020	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

Midland County Health Dept.  
220 West Ellsworth  
Midland, MI 48640-5194  
989 832-6679

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

Report To: BEN LARSON  
4011 W ISABELLA  
SHEPHERD MI 48883

Sample ID: LJ09523  
Work Order: 00603291\_03

System Name/Owner: WEST MIDLAND FAMILY CENTER  
Collection Address: 4011 W ISABELLA, SHEPHERD  
Collected By: BEN LARSON  
Township/Well#/Section: GREENDALE/5/15  
County: Midland  
Sample Point: 116A  
Water System: Untreated Public Distribution System

WSSN/Pool ID: 2002156  
Source: TYPE II  
Site Code:  
Collector: Other  
Date Collected: 06/24/2020 08:15  
Date Received: 06/24/2020 12:57  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	0.13	mg/L	0.05	06/25/2020	1.3	EPA 200.8	7440-50-8
Lead	0.002	mg/L	0.001	06/25/2020	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

Midland County Health Dept.  
220 West Ellsworth  
Midland, MI 48640-5194  
989 832-6679

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane

Official Laboratory Report

Report To: BEN LARSON  
4011 W ISABELLA  
SHEPHERD MI 48883

Sample ID: LJ09524  
Work Order: 00603291\_04

System Name/Owner:	WEST MIDLAND FAMILY CENTER	WSSN/Pool ID:	2002156
Collection Address:	4011 W ISABELLA, SHEPHERD	Source:	TYPE II
Collected By:	BEN LARSON	Site Code:	
Township/Well#/Section:	GREENDALE/5/15	Collector:	Other
County:	Midland	Date Collected:	06/24/2020 08:15
Sample Point:	207	Date Received:	06/24/2020 12:57
Water System:	Untreated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	06/25/2020	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	06/25/2020	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

Midland County Health Dept.  
220 West Ellsworth  
Midland, MI 48640-5194  
989 832-6679

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

Report To: BEN LARSON  
4011 W ISABELLA  
SHEPHERD MI 48883

Sample ID: LJ09525  
Work Order: 00603291\_05

System Name/Owner:	WEST MIDLAND FAMILY CENTER	WSSN/Pool ID:	2002156
Collection Address:	4011 W ISABELLA, SHEPHERD	Source:	TYPE II
Collected By:	BEN LARSON	Site Code:	
Township/Well#/Section:	GREENDALE/5/15	Collector:	Other
County:	Midland	Date Collected:	06/24/2020 08:15
Sample Point:	307A OLD GYM	Date Received:	06/24/2020 12:57
Water System:	Untreated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	06/25/2020	1.3	EPA 200.8	7440-50-8
Lead	0.005	mg/L	0.001	06/25/2020	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

Midland County Health Dept.  
220 West Ellsworth  
Midland, MI 48640-5194  
989 832-6679

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		